

Project - Quarterly Progress Report

| | | |
|-------------------------|---|-----------------------------------|
| Promoter's Name | : | Casa Grande Coimbatore LLP |
| Project Name | : | Casagrand Aqua |
| Project Registration No | : | TN/11/Building/0214/2017 |
| Quarter Ending | : | 31st March 2019 |

A. Sales

| S.No | Description | Nos. | | Total Area (Sq.m) |
|------|--|---------|----|-------------------|
| 1. | Plots/Flats Booked size wise (As given in Carpet Area Statement while registering) | 2BHK+1T | 39 | 2263.29 |
| | | 2BHK+2T | 15 | 1620.26 |
| | | 3BHK+3T | 24 | 4014.77 |
| | | 4BHK+4T | 13 | 3015.24 |
| 2. | Parking Lots | 68 | | 850.00 |
| 3. | UDS Registered in Sq.m. | 18 | | 1965.25 |

B. Construction

| S.No | Description | Block/Tower No. | Status |
|------|---|-----------------|---|
| 1. | Stage of construction of each Block/Tower, Floor wise | 1 to 10 | External Plastering in progress |
| | | 11 to 18 | Block work in progress |
| | | 19 to 30 | Painting work in progress |
| | | 31 to 42 | Painting work in progress |
| | | 45 to 55 | Block work in progress |
| | | 56 to 66 | Plastering in progress |
| | | 68 to 77 | First floor roof slab works in progress |
| | | 78 to 83 | Ground floor columns completed |
| | | 84 to 88 | First floor column works in progress |
| | | A - 2BHK + 2T | Third Floor block work in progress |
| | | B - 2BHK + 1T | Plastering in progress |

| | | | |
|----|--|------------|------------------------|
| 2. | Status of common Amenities for each Block/Tower, Item wise | Club House | Excavation in progress |
|----|--|------------|------------------------|

C. Details of Clearances

1. Completion Certificate No. **NA**
2. Annual Audit Report of Special Account in Form 7 **Already Submitted**

D. Latest Photo with Date (Atleast from 2 angles) – Enclosed in CD



Regular 2BHK



Smart 2BHK



STP, WTP



V.No. 1 to 10



V.No. 11 to 18



V.No. 19 to 30



V.No. 31 to 42



V.No. 45 to 55



V.No. 56 to 66



V.No. 68 to 77



V.No. 78 to 83



V.No. 84 to 88